. 1	Burnside Initial Incident Report	
	(for internal use only)	
	Incident Information	
Date reported:	9-12	_
Title:	ator	
Incident data		
3 - 18 Area: 5/	Not sure	
Brief Description of know	th Fence Perimeter	
line toward	1 a DOS LEGIK CINSSING FONCE	
Immediate action taken:	115Dection as per Home land securit	y r
truck wou	not move stock was getting off.	5/2
Other action recommender Environmental deviation(1	Title V, other):	
Chemical released:	CONTacted Kerry Long & Liz Crom, had Jennie + CNEW F	w
70,2	nad U Lannie + Cnew f	X
Report Completed by:	TERR Simples	

Note: Deliver copy of form to manager upon completion





Burnside Initial Incident Report

(for internal use only)

Incident Information		
Date reported: 3/19/2012		
Title: CIP Gas-Leak		
Incident date: 3/18/2012 Incident time: Approx. 8:30p.m.		
Area: CIP/HIP Exchanger		
Brief Description of known facts: A gas leak on the CIP Exchanger was noticed by the outside operator		
Immediate action taken: contacted supervision and environmental coordinator. Environmental coordinator responded first, advised to contact mark if gas leak was going off site.		
Other action recommended:		
Environmental deviation(Title V, other): None		
Chemical released: Gas mixture SO2/SO3		
Report Completed by: E. Cromwell		

Note: Deliver copy of form to manager upon completion

